State of Oregon Drinking Water Program Monthly Disinfection Report for Ground Water Systems

System Name Idaho Power- Oxbow Village PWS ID# 4 1 00384							
EP-B, Entry Point for Month/Year Feb/2021 Entry Point: Copperfield Park Well Required Minimum Residual 0.2 mg/L							
Date	Time	Source(s) in use		Lowest free chlorine residual at entry point to distribution system (mg/L		Notes	
1	0700	Booster Pump		.35	House 5620		
2	0700	Booster Pump		.34			
3	0700	Booster Pump		.35			
4	0700	Booster Pump		.24	House 565 .14		
5	0700	Booster Pump		.26			
6	0700	Booster Pump		.36			
7	0700	Booster Pump		.37			
8	0640	Booster Pump		.46	House 5613 .26		
9	0700	Booster Pump		.45			
10	0645	Booster Pump		.47			
11	0700	Booster Pump		.43	House 851 .31		
12	0700	Booster Pump		.40			
13	0700	Booster Pump		.42			
14	0700	Booster Pump		.37			
15	0700	Booster Pump		.37	House 5620	.28	
16	0700	Booster Pump		.39			
17	0700	Booster Pump		.37			
18	0700	Booster Pump		.37	House 565	.26	
19	0700	Booster Pump		.36			
20	0700	Booster Pump		.36			
21	0700	Booster Pump		.35			
22	0700	Booster Pump		.34	House 5613 .24		
23	0800	Booster Pump		.35			
24	0800	Booster Pump		.35			
25	0700	Booster Pump		.37	House 851	.26	
26	0700	Booster Pump		.36			
27	0700	Booster Pump		.34	_		
28	0700	Booster Pump		.36			
29		Booster Pump					
30		Booster Pump					
31 Booster Pump							
Was the chlorine residual ever less than the required minimum residual of 0.2 mg/L? Yes No lf yes, what was the longest time period until the required level was restored?							
GWS	Serving	3,300 or Fewer		GWS Serving More Than 3,300			
If yes, did you monitor every four hours until the residual returned to 0.2 mg/L? □Yes □ No Attach those results and submit them with this form.				monitoring equipment fail at a		Date continuous monitoring equipment failed:	
			If yes, were grab samples collected every four hours until the continuous monitoring equipment was returned to service? Yes No		Date it was returned to service:		
			Attach grab san	ample results and submit them with this form			
Printed N	lame: Tim Fe	erguson	Title: Field Engineer		Operator Certification #:		
Signature	: 17		Phone #: (541) 785-7293		OR		
Date: 03	/ 08/2021				Small Groundwater System ⊠		